

Assessment Results Exceedance Table

At Westorchard Elementary School, 4 (3.6%) out of the 110 samples collected from outlets required to be tested by the NY DOH emergency regulation had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Westorchard Elementary School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
09/23/16	WES-38	1 st	Hand washing sink in kitchen	52.8
09/23/16	WES-51	1 st	Sink in Boy's Gym PE Office Bathroom	19.4
09/23/16	WES-103	2 nd	Sink in Room C3 Hose	15.5
09/23/16	WES-104	2 nd	Fountain in Room C4	18.7

At the Roaring Brook Elementary School, 4 (4.4%) out of the 90 samples collected from outlets required to be tested by the NY DOH emergency regulation had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Roaring Brook Elementary School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
09/23/16	RBES-03	Bsmt	Sink PO CCW 2 Room	105
09/23/16	RBES-09	1 st	Prep Sink in Kitchen (left)	37.2
09/23/16	RBES-65	1 st	Sink in Room 109	21.5
09/23/16	RBES-71	2 nd	Sink in Room 201	25.0
09/23/16	RBES-92	Exterior	Hose Bib by Loading Dock	34.1

At the Douglas Grafflin Elementary School 2 (1.6%) out of the 123 samples collected from outlets required to be tested by the NY DOH emergency regulation had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Douglas Grafflin Elementary School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
09/23/16	DGES-58	Upper	Third Sink in South Wing Room 225	36.5
09/23/16	DGES-99	Upper	Sink in Annex Kindergarten Room 1	17.2

At the Robert Bell Middle School, 19 (19.8%) out of the 96 samples collected from outlets required to be tested by the NY DOH emergency regulation had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Robert Bell Middle School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
09/23/16	RBMS-25	2 nd	Sink in Room 214A Toilet	37.8
09/23/16	RBMS-28	2 nd	Sink in Electrical Panel Room near Gym	180
09/23/16	RBMS-36	3 rd	Sink in Room 300 Small space near entrance	1700
09/23/16	RBMS-49	3 rd	First Sink in Room 348	41.8
09/23/16	RBMS-50	3 rd	Second Sink in Room 348	39.9
09/23/16	RBMS-51	3 rd	Third Sink in Room 348	54.1
09/23/16	RBMS-54	3 rd	Sixth Sink in Room 348	27.1
09/23/16	RBMS-57	3 rd	Third Sink in Room 346	62.1
09/23/16	RBMS-60	3 rd	Sixth Sink in Room 346	166
09/23/16	RBMS-62	3 rd	Fifth Sink in Room 344	112
09/23/16	RBMS-63	3 rd	Fourth Sink in Room 344	86.2
09/23/16	RBMS-68	3 rd	First Sink in Room 342	16.4
09/23/16	RBMS-71	3 rd	Fourth Sink in Room 342	141
09/23/16	RBMS-80	3 rd	Seventh Sink in Room 340	135
09/23/16	RBMS-81	3 rd	Sink in Room 340 Storage Closet	108
09/23/16	RBMS-84	3 rd	Third Sink in Room 338	54.7
09/23/16	RBMS-87	3 rd	Sixth Sink in Room 338	26.1
09/23/16	RBMS-91	3 rd	Fourth Sink in Room 336	501
09/23/16	RBMS-96	3 rd	Third Sink in Room 334	57.9
09/23/16	RBMS-103	Exterior	Hose bib outside PTA Office	136
09/23/16	RBMS-104	Exterior	Hose bib outside Garden Area	35.9

At the Seven Bridges Middle School, 11 (9.8%) out of the 112 samples collected from outlets required to be tested by the NY DOH emergency regulation had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Seven Bridges Middle School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
09/23/16	SBMS-27	1 st	Sink B in Classroom 209	22.8
09/23/16	SBMS-29	1 st	Sink D in Classroom 209	45.4
09/23/16	SBMS-30	1 st	Left Sink in Prep Room to 209	24.2
09/23/16	SBMS-31	1 st	Right Sink in Prep Room to 209	48.4
09/23/16	SBMS-76	1 st	Sink D in Classroom 222	22.9
09/23/16	SBMS-89	2 nd	Sink E in Classroom 309	42.8
09/23/16	SBMS-90	2 nd	Left Sink in Prep Room to Classroom 309	55.8
09/23/16	SBMS-91	2 nd	Right Sink in Prep Room to Classroom 309	17.2
09/23/16	SBMS-105	2 nd	Sink B in Classroom 319	16.7
09/23/16	SBMS-109	2 nd	Left Sink in Prep Room to Classroom 319	24.6
09/23/16	SBMS-110	2 nd	Right Sink in Prep Room to Classroom 319	120

Assessment Results Exceedance Table

*Any samples collected from drinking fountains with concentrations of lead over 15 ppb are indicated in **red**.*

Of the 210 samples collected at Horace Greeley High School, 38 (18.1%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Horace Greeley High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/08/16	HGHS-34	1 st	Sink in Gym A, Girls Locker Room Coaches RR	266
10/08/16	HGHS-43	1 st	Sink in Room C4 (Left)	27.8
10/08/16	HGHS-79	2 nd	Sink in Room J 206 (4, Right)	51.1
10/08/16	HGHS-81	2 nd	Sink in Room J 206 (6, Right)	17.6
10/08/16	HGHS-86	2 nd	Sink in Room J 206 Teachers (7)	29.1
10/08/16	HGHS-87	2 nd	Sink in Room J 204 Teachers Desk	16.7
10/08/16	HGHS-89	2 nd	Sink in Room J 204 (1, Right)	15.1
10/08/16	HGHS-113	2 nd	Sink in Room K 206 Teachers Desk	58.0
10/08/16	HGHS-116	2 nd	Sink in Room K 205 (2, Left)	137
10/08/16	HGHS-119	2 nd	Sink in Room K 205 (3, Right)	51.1
10/08/16	HGHS-121	2 nd	Sink in Room K 205 (4, Right)	21.5
10/08/16	HGHS-124	2 nd	Sink in Room K 205 (6, Left)	30.3
10/08/16	HGHS-125	2 nd	Sink in Room K 205 (6, Right)	17.5
10/08/16	HGHS-126	2 nd	Sink in Room K 205 Teachers Desk	20.4
10/08/16	HGHS-127	2 nd	Sink in Room K 208 Teachers Desk (Left)	37.5
10/08/16	HGHS-128	2 nd	Sink in Room K 208 Teachers Desk (Right)	17.4
10/08/16	HGHS-133	2 nd	Sink in Room K 207 Teachers Desk (Right)	53.9
10/08/16	HGHS-134	2 nd	Sink in Room K 207 Back	120
10/08/16	HGHS-149	2 nd	Sink in Room J 103 Teachers Desk	33.6
10/08/16	HGHS-156	2 nd	Sink in Room J 106 (4, Left)	21.9
10/08/16	HGHS-157	2 nd	Sink in Room J 106 (4, Right)	16.8
10/08/16	HGHS-158	2 nd	Sink in Room J 106 (5, Left)	16.8
10/08/16	HGHS-162	2 nd	Sink in Room J 106 Teachers Desk	128
10/08/16	HGHS-165	1 st	Sink in Room J 104 (2, Left)	17.7
10/08/16	HGHS-175	1 st	Sink in Room J 104 Teachers Desk	112
10/08/16	HGHS-180	1 st	Sink in Room K 105 (1)	76.6
10/08/16	HGHS-181	1 st	Sink in Room K 105 (2)	78.0
10/08/16	HGHS-182	1 st	Sink in Room K 105 (3)	260
10/08/16	HGHS-183	1 st	Sink in Room K 105 (4)	217
10/08/16	HGHS-184	1 st	Sink in Room K 105 (5)	51.7

Horace Greeley High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/08/16	HGHS-187	1 st	Sink in Room K 105 (8)	56.7
10/08/16	HGHS-188	1 st	Sink in Room K 105 (9)	30.2
10/08/16	HGHS-192	1 st	Sink in Room K 105 (13)	27.4
10/08/16	HGHS-194	1 st	Sink in Room K 105 Teachers Desk (15)	44.5
10/08/16	HGHS-197	1 st	Sink in Room K 102 Teachers Desk (1)	49.2
10/08/16	HGHS-201	1 st	Sink in Room K 101 (1)	37.1
10/08/16	HGHS-203	1 st	Sink in Room K 101 (3)	35.0
10/08/16	HGHS-208	1 st	Slop sink in Gym A	47.8